



Photograph 1: Vehicle storage area located in the central portion of the subject property.



Photograph 2: View of the northeastern portion of the subject property.



Photograph 3: View of the north-central portion of the subject property.



Photograph 4: View of the northwestern portion of the subject property.



Photograph 5: View of the southwestern portion of the subject property.



Photograph 6: View of the south-central portion of the subject property.




Photograph 7: View of the southeastern portion of the subject property; the 2,500 gallon water AST is located in the southeastern portion of the subject property.



Photograph 8: Water tower associated with Instant Jungle tenant space.



Photograph 9: 1,000 gallon empty AST located on the northeastern portion of the subject property.






Photograph 10: ASTs and minor staining observed in the northwestern portion of the subject property.



Photograph 11: ASTs observed in the south-central portion of the subject property.



Photograph 12: Minor staining was observed in the vicinity of the ASTs located in the south-central portion of the subject property.



Photograph 13: 55-gallon drums observed on the south-central portion of the subject property.



Photograph 14: 5 gallon buckets of hydraulic oil located on the eastern portion of the subject property.





Photograph 15: Chemical storage observed in tenant space located along the northern portion of the subject property.



Photograph 16: 55-gallon drums and plastic totes observed in the central portion of the subject property.



Photograph 17: Non-operational transformer awaiting to be sold.




Photograph 18: Desilting basin located on the northeastern portion of the subject property.



Photograph 19: Drainage ditch located along the southern boundary of the subject property.



Photograph 20: Dirt piles observed on the northeastern portion of the subject property.



Baker Ranch Properties

NWC Portola Pkwy/Rancho Pkwy Foothill Ranch, CA 92610

Inquiry Number: 3797354.5

December 03, 2013

The EDR Aerial Photo Decade Package



EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc., All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Date EDR Searched Historical Sources:

Aerial Photography December 03, 2013

Target Property:

NWC Portola Pkwy/Rancho Pkwy Foothill Ranch, CA 92610

<u>Year</u>	<u>Scale</u>	<u>Details</u>	<u>Source</u>
1938	Aerial Photograph. Scale: 1"=500'	Flight Year: 1938	Laval
1946	Aerial Photograph. Scale: 1"=500'	Flight Year: 1946	Jackmann Air
1953	Aerial Photograph. Scale: 1"=500'	Flight Year: 1953	Pacific Air
1960	Aerial Photograph. Scale: 1"=500'	Flight Year: 1960	Fairchild
1972	Aerial Photograph. Scale: 1"=500'	Flight Year: 1972	EDR
1977	Aerial Photograph. Scale: 1"=500'	Flight Year: 1977	Teledyne
1990	Aerial Photograph. Scale: 1"=500'	Flight Year: 1990	USGS
1994	Aerial Photograph. Scale: 1"=500'	/DOQQ - acquisition dates: 1994	EDR
2005	Aerial Photograph. Scale: 1"=500'	Flight Year: 2005	EDR
2009	Aerial Photograph. Scale: 1"=500'	Flight Year: 2009	EDR
2010	Aerial Photograph. Scale: 1"=500'	Flight Year: 2010	EDR
2012	Aerial Photograph. Scale: 1"=500'	Flight Year: 2012	EDR

